



NGCP

Stronger transmission
for a stronger nation.

NGCP-VOM-D1-14- 02-11

August 28, 2014

Mr. Marlon B. Roa
General Manager
Biliran Electric Cooperative, Inc.
Brgy. Caray-caray, Naval, Biliran

Dear GM Roa:

We regret to inform you that the series of power interruptions experienced by BILECO yesterday evening starting at 1945H were caused by an unretrieved broken woodpole that leaned to the loop jumper of the Phase B conductor of Str. # 155-3T located at Brgy. Tinucdugan, Leyte, Leyte along the 69kV Lemon - Biliran line.

After removal of the line obstruction, power was restored at 0121H this morning.

We are sorry for the inconvenience.

Sincerely,


LOPE L. CANETE
Head
District 1, Leyte/Samar Area

cc: *MS. MA ROSETTE B. MARTINEZ*, Visayas Corp. Comm. Officer
MS. MA. EDNA P. LEGASPINA, Head, Visayas Corporate Affairs
MR. GERARDO A. TORRES, Department Head, Visayas O&M